


Montageanleitung - Mounting Instruction

KI-ST 2 KLD



Montagereihenfolge:

1. Bohrung mindestens 23 mm
2. Edelstahlscheibe bis zum Anschlag auf das Rohr schieben
3. Dichtungsscheibe bis unter die Edelstahlscheibe schieben
4. Standrohr in die Bohrung stecken
5. Das Steckdosengehäuse in die gewünschte Position drehen
6. Mittels Mutter und Sicherungsscheibe das Gehäuse fest andrehen
Achtung das Gehäuse läßt sich nur bei gelöster Mutter in eine andere Position drehen
7. Elektroanschluß 230 Volt vornehmen.

Technische Daten: Steckdoseneinsätze 230 Volt/50 Hz, Gesamtbelastbarkeit 16 Ampere

Mounting Steps:

1. Make the Cut hole 23 mm
2. Move the stainless steel plate to the stop onto the pipe
3. Move the washer to below the stainless steel plate
4. Place the pipe into the hole
5. Turn the socket element in the right position
6. With the nut and lock washer tighten the housing
Please note that the housing can only dissolved by a mother other position
7. Make the connection with the main voltage
Main Voltage: 250 Volt 50 Hz - total Power 13 Amps