







Montagefolge APS 11

Bestückung:

Art.Nr. 17126 S = 3 x Steckdose mit Schutzkontakt 240 Volt / 16 Ampere

17116 S = 2 x Steckdose mit Schutzkontakt 240 Volt / 16 Ampere 2 x USB Port mit Ladegerät 5V/1000 mA

Equipment:

Art.No. 17126 S = 3 x socket with protective contact 240 Volt / 16 Ampere

17116 S = 2 x socket with protective contact 240 Volt / 16 Ampere 2 x USB port with charger 5V/1000 mA

D

! Achtung: Alle Montagearbeiten in spannungslosen Zustand durchführen. Bitte beachten Sie die jeweils gültigen VDE Richtlinien. Änderungen an den Elementen oder deren Bauteile sind nicht gestattet

Reinigungshinweis:

Um Beschädigungen an der Oberfläche zu vermeiden, bitte keine Scheuermittel und Putzschwämme verwenden! Verwenden Sie nur für Edelstahl geeignete silikonhaltige Reinigungsmittel!

UK

! Attention: Carry out all assembly work in a de-energized state. Please observe the applicable DIN VDE 0100 guidelines or national rules. Modifications to the elements or their components are not permitted.

Cleaning instructions:

To avoid damage to the surface, please do not use scouring agents and cleaning sponges! Use only silicone-containing cleaning agents suitable for stainless steel!